

The Most Comprehensive Portable PQA on The Market

Catch Power Quality Problems on the Fly...

- Monitor for:
 - Inrush Current
 - Voltage Swells
 - Voltage Dips
 - Transient Overvoltage
 - Interruptions
- Measure and Record:
 - Power and Power Factor
 - Active/Reactive Energy Demand
 - Load Changes (with graph display!)
 - Voltage and Current



USB 2.0
STANDARD
(for data transfer only)

True RMS


9661×3 (option)



SPECIFICATIONS	
Measurable Circuits	1P2W/1P3W/3P3W2M/3P3W3M/3P4W/3P4W2.5E
Measurement Line Frequency	Auto-detect (50Hz/60Hz)
Voltage Range	600.0V
Current Range	Manually Switchable from 2 Range Sets According to Clamp Sensor 500.0mA/5.000A/50.00A/10.00A/100.0A/500.0A/1.000kA/5.000kA
Measurement Function	1. Transient overvoltage 2. Voltage swell, Voltage dip, Voltage interruption 3. Frequency, Voltage, Current, Voltage/Current peak, Active/Reactive/Apparent power, Power factor, DPF 4. Voltage unbalance ratio 5. Harmonic voltage/current/power, Harmonic voltage current phase angle, Total harmonic distortion 6. Inrush current
Interval Settings	AUTO/1/5/10/15/30/60 minutes
Maximum Recordable Period	125 Days with internal non-volatile memory of 4MB - stored data will not be deleted upon power OFF; partition memory into 4 segments for maximum 31 days of recording each
Internal Memory	4MB
PC Interface	USB Ver.2.0 (for data transfer only)
Power supply	9418-15 AC Adapter or 9459 Battery Pack
Dimensions and Mass	128W × 246H × 63D mm, 1.2 kg with battery pack
Accessories	Voltage cords (4), BATTERY PACK (1), AC ADAPTER (1), USB Cable (1), Basic PC Software (1), Carrying Case (1), Strap (1)

OPTIONS

CLAMP ON SENSOR 100A AC	9660
CLAMP ON SENSOR 500A AC	9661
FLEXIBLE CLAMP ON SENSOR 5000A AC	9667
CLAMP ON SENSOR 1000A AC	9669
CLAMP ON SENSOR 5A AC	9694
CLAMP ON SENSOR 50A AC	9695-02
CLAMP ON SENSOR 100A AC	9695-03
CONNECTION CORD (for the 9695-02/9695-03)	9219
CLAMP ON LEAK SENSOR 10A AC	9657-10
CLAMP ON LEAK SENSOR 10A AC	9675
VOLTAGE CORDS (bundled with standard 3197)	9438-05
BATTERY PACK (bundled with standard 3197)	9459
PQA HiVIEW PRO (PC application software)	9624-50
AC ADAPTER (for the 9667, for America, Japan)	9445-02
AC ADAPTER (for the 9667, for Europe)	9445-03



Industrial Supply Syndicate
 54, Ezra Street, Kolkata - 700 001, INDIA
 Phone: 22350923, 22356676 Fax: +91 33 30222923
 Email: info@industrialindia.com Website: www.industrialindia.com